


LiquiBand[®] Flow Control

The ideal solution for rapid polymerization and superior control.



LIQUIBAND[®] TECHNOLOGY

Better wound closure starts with a better tool



Application Guide LiquiBand[®] Flow Control

STEP ONE

- Ensure that wound is thoroughly clean and dry prior to closure.
- While holding upright, twist and snap off the winged cap.
- Affix the applicator tip with gentle pressure (optional).

📀 STEP TWO

Invert the tip and gently squeeze to prime the device.
When the tip fills with adhesive, LiquiBand[®] Flow Control is ready to use.

STEP THREE

- While holding the wound edges together, apply an even coat of LiquiBand[®] Flow Control over the length of the wound.
- Continue to hold the wound edges together for 30 seconds.

LiquiBand[®] Flow Control





T +44 (0) 1752 209 955

E info@liquiband.comW liquiband.com

IRM 06 0253

Advanced Medical Solutions Limited, Western Wood Way, Langage Science Park, Plymouth, Devon, PL7 5BG, UK © 2018. LiquiBand® and LiquiBand® Exceed™ are registered trademarks of Advanced Medical Solutions Limited.